


Access control system upgrade at Library Main Entrance 20 Jul - 16 Aug 2015



Temporary Guard Post and Access Control System

Work Area with hoarding

Temporary Library Entrance

Wiring work of LAN port from the Server to the Main Entrance at ceiling (it depends on on-site inspection)

Electrical Wiring work from Main Switch Box to Main Entrance at ceiling (It depends on on-site inspection)